Repair Hitachi Aloka F37 TX Ultrasound Machine Parts Board EP557400

Basic Information

. Place of Origin: Japan

. Brand Name: HITACHI ALOKA EP557400 Model Number: Minimum Order Quantity: 1pc • Price: negotiable Packaging Details: carton . Delivery Time: 3-5 days

• Payment Terms: T/T, Western Union • Supply Ability: 10-30pcs/month



Product Specification

• Warranty: 60 Days After Fixed Lead Time: 3-5 Working Days

. Service: Repair

• Shipping Method: Express, or As Clients Required

• Highlight: EP557400 Ultrasound Machine Parts Board, Hitachi Aloka Ultrasound Machine Parts Board



More Images



Product Description

Repair Hitachi Aloka F37 RX Ultrasound Machine Parts Board EP557400

1. Part number: EP557400

2. Type: TX board

3. Trade term: repair service are provided.

4. Warranty: 60 days



More details welcome to contact with us!

Something about Hitachi Aloka F37 ultrasound machine:

Features :

- AIP Adaptive Image Processing
- SCI Spatial Compound Imaging
- BbH Broadband Harmonics
- Image Optimizer
- Simple Switch Operation
- Compact ergonomic design
- Large capacity hard drive
- eFLOW
- Auto Angle Correct for Doppler
- SIP Silky Image Processing
- Real-Time 3D/4D
- 4D Shading
- AVM Auto Volume Measurement
- Zoom
- eFlow
- MPR MultiPlanar Reconstruction
- CPWG Compound Pulse Wave Generator
- SmartProbes

Applications:

4D, Abdominal, Anesthesia, Breast, General Imaging, Musculoskeletal, OB-GYN, Peripheral Vascular, Small Parts, Superficial, Thyroid, Vascular, Venous. Applications:

4D, Abdominal, Anesthesia, Breast, General Imaging, Musculoskeletal, OB-GYN, Peripheral Vascular, Small Parts, Superficial, Thyroid, Vascular, Venous



+8619536805795

info@volka-medtech.com



3dultrasoundprobe.com

Office 5, 8/F, Mega Cube, 8 Wang Kwong Road, Kowloon Bay, KowLoon, Hong Kong