

## Repair GE Logiq S8 Original Ultrasound Beamformer BF192 Board 5357234-2

Our Product Introduction

### Basic Information

- Place of Origin: USA
- Brand Name: GE
- Model Number: 5357234-2
- Minimum Order Quantity: 1pc
- Price: negotiable
- Packaging Details: carton
- Delivery Time: 3-5 days
- Payment Terms: T/T, Western Union
- Supply Ability: 10-30pcs/month



### Product Specification

- Warranty: 60 Days After Fixed
- Lead Time: 3-5 Working Days
- Service: Repair
- Shipping Method: Express, or As Clients Required
- Highlight: **GE Logiq S8 Ultrasound Beamformer Board, Original Ultrasound Beamformer Board, 5357234-2 Ultrasound Beamformer Board**



### More Images



for more products please visit us on [3dultrasoundprobe.com](http://3dultrasoundprobe.com)

## Product Description

### Repair GE Logiq S8 Original Ultrasound Beamformer BF192 Board 5357234-2

| Attribute       | Value                           |
|-----------------|---------------------------------|
| Warranty        | 60 days after fixed             |
| Lead time       | 3-5 working days                |
| Service         | Repair                          |
| Shipping method | Express, or as clients required |

### Product Details

Part number: 5357234-2

Type: BF192 beamformer board

Trade term: Repair service provided

Warranty: 60 days after repair completion

Repair time: 3-5 working days (for previously unfixed units with normal image faults)



For more details, please contact our technical support team.

### Compatible GE Systems We Service

| Brand | System   | Description                | Part Number             |
|-------|----------|----------------------------|-------------------------|
| GE    | Logiq P5 | APS power supply           | 5140505/5166108/5329667 |
| GE    | Logiq P5 | CPU on SYSCONPM            | 5168431                 |
| GE    | Logiq P5 | SYSCONPM                   | 5177848-3               |
| GE    | Logiq P6 | APS II DC/PST power supply | 5245004/5244555         |
| GE    | Logiq P6 | SOM (CPU) on SYSCONML      | 5252251                 |
| GE    | Logiq P6 | SYSCONML with SOM          | 5252326-3/5252250-3     |

|    |                         |                           |                             |
|----|-------------------------|---------------------------|-----------------------------|
| GE | Logiq S7/Logiq S8       | CPS Power supply          | 6626600 R02/5413249-3       |
| GE | Logiq S7                | GBF128 transmitting board | 5392446,5392446-3           |
| GE | Logiq S7                | mainboard GFS Assy        | 5371196                     |
| GE | Logiq S8                | BF192                     | 5357234/5357234-2           |
| GE | Logiq S8                | mainboard GFS Assy        | 5371196-2/5455247           |
| GE | Vivid E80 E90 E95       | CRX Receiver board        | GC200002                    |
| GE | Logiq E9                | MRX Board                 | 5393908/5393912             |
| GE | Logiq E9/vivid E9       | GTX/GTX-TLP192            | GA200726                    |
| GE | Logiq E9/vivid E9       | GFI2                      | 5161631                     |
| GE | Logiq E10 E11 E20       | ETX128 channel PWA        | 5321216-4                   |
| GE | Voluson E6/Voluson E8   | RSR                       | KTI301394-2/KTI196357       |
| GE | Voluson E6/Voluson E8   | RST                       | KTI301148                   |
| GE | Voluson E6/E8/E10       | RSX                       | KTZ303054 /KTI303054        |
| GE | Voluson E6/E8/E10       | RFM201 FE mainboard       | KTZ303916                   |
| GE | Voluson E6/E8/E10       | RFM221 FE mainboard       | KTZ303915                   |
| GE | Voluson E6/E8/E10       | RFM423 FE-Mainboard       | KTZ304142/KTZ304074/5729200 |
| GE | Voluson E8/E10          | RFM323 FE-Mainboard       | 5279044-4/5729044-7         |
| GE | Voluson E6/Voluson E8   | RFI20/ RFI21b Board       | KTI300614/KTI302197_6       |
| GE | Voluson S6/S8/S10/P6/P8 | DBM64                     | 5573639-2/ 5773603          |
| GE | Voluson S6/S8/S10/P6/P8 | DBM128/DBM128S            | 5573638-2/5573638           |
| GE | Voluson S6/S8/P8        | BF64                      | 5396937-2                   |
| GE | Voluson S6/S8/P8        | BF128                     | 5338209-2/5728962           |
| GE | Voluson S6/S8/P8        | CPS Power supply          | 5393431/6002001             |
| GE | Voluson S6/S8/P8        | RFS board                 | 5364098-2/5364098-3         |

## Frequently Asked Questions

### Q: What is the MOQ?

A: 1pc.

### Q: How about your delivery time?

A: 1~15 days depends on your order quantity.

### Q: What is your terms of delivery?

A: DHL, TNT, EMS, UPS, FedEx, also can use customer's freight forwarder.

### Q: What is your terms of payment?

A: Western union, T/T in advance.

### Q: Do you test all your goods before delivery?

A: Yes, we have 100% tested our goods before delivery.

### Q: What is your Service & Return policy?

A: If the probe is not compatible with your machine or there are any quality problem within 7 days after receiving the goods, please feel free to contact us. We will send a replacement probe or refund the payment to you.



+852 9070 6664



info@volka-medtech.com



3dultrasoundprobe.com

Office 5, 8/F, Mega Cube, 8 Wang Kwong Road, Kowloon Bay, KowLoon, Hong Kong